

**COLOR AVAILABLE**

› Refer to Stock Service Color Card

**INDUSTRIAL FINISHING**

- After knitted process stabilize the panel by steaming or immersing in hot water, cooling them off in water, and softening at 30 degrees using the products of your choice on a delicate-fabrics wash cycle; then it should be given another spin. You may need to accommodate the fabric after spinning; this should be done with a manual steam iron before starting the drying process.

**CARE INSTRUCTION**

Hand Wash

Any solvent  
except  
tetrachloroethylene

Iron low



Do not bleach



Dry Flat

**COLOR FASTNESS (AVERAGE VALUES)**

	Dry rubbing	Wet rubbing	Wash fastness
Light	4	4	4
Medium	4	3	4
Dark	3	2/3	3

**TECHNICAL INFORMATION**

Dyeing method	hanks
Knot type	splicer
Pilling	3.5

**KETTLE SIZE (Kg.)**

hanks	tops
30	50
40	100
80	200
200	

**CERTIFICATION****SUGGESTED GAUGE**

7gg ~ 10gg

**NOTES:**

- Might occur bleeding in designs with white stripes and intense colors.
- Consult our sales team about dyeing process that decrease bleeding risk on intense colors.
- For minimum production quantities and customers' own colors please contact our sales representative or write us to essentials@incatops.com.
- Minimum for dark colors subject to revision.